SEE DN67 NOTICE LETTER FOR APPLICABLE LAST TIME BUY TERMS, CONDITIONS AND CODE DEFINITIONS FOR THESE DISCONTINUED PRODUCTS. FOR ADDED INFORMATION, REFER TO NXP WEB-SITE "http://www.nxp.com/products/eol/"

TYPE CODE:

SOURCE CODE

T = Type number fully withdrawn

N = Part type package only withdrawn

C = Customer Specific Product M = Multiple Source Product S = Sole Source Product

AVAILABILITY CODE:

1 = Non-availability. No last time buy possible

2 = Limited Availability (check with your usual sales contact)

3 = Standard Availability

| Type Number | NXP Type Number | Description | 12NC | Discontinuation Type Code | Source Code | Availability Code | Last Time Buy Date | Last Time Delivery Date | Replacement Part | Customer Comments |
|----------------|--------------------|--------------------------------|--------------|------------------------------|----------------|----------------------|-----------------------|-------------------------------|---------------------|---|
| 1PS76SB10/DG | | Schottky diode | 934061933115 | N | М | 3 | 30-Jun-11 | 31-Dec-11 | 1PS76SB10 | Standard End Of Life. |
| 1PS79SB30/DG | | Schottky diode | 934061176115 | N | М | 3 | 30-Jun-11 | 31-Dec-11 | 1PS79SB30 | Standard End Of Life. |
| 74ABT16821ADGG | 74ABT16821ADGG,112 | MB/ABT16 | 935203250112 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | TI: SN74ABT16821 | Standard End of Life. |
| 74ABT16821ADGG | 74ABT16821ADGG,118 | MB/ABT16 | 935203250118 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | TI: SN74ABT16821 | Standard End of Life. |
| 74ABT16821ADL | 74ABT16821ADL,512 | MB/ABT16 | 935196760512 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | TI: SN74ABT16821 | Standard End of Life. |
| 74ABT16821ADL | 74ABT16821ADL,518 | MB/ABT16 | 935196760518 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | TI: SN74ABT16821 | Standard End of Life. |
| 74ABT16841ADGG | 74ABT16841ADGG,112 | MB/ABT16 | 935203270112 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | TI: SN74ABT16841 | Standard End of Life. |
| 74ABT16841ADGG | 74ABT16841ADGG,118 | MB/ABT16 | 935203270118 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | TI: SN74ABT16841 | Standard End of Life. |
| 74ABT16841ADL | 74ABT16841ADL,512 | MB/ABT16 | 935196770512 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | TI: SN74ABT16841 | Standard End of Life. |
| 74ABT16841ADL | 74ABT16841ADL,518 | MB/ABT16 | 935196770518 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | TI: SN74ABT16841 | Standard End of Life. |
| 74ABT2240D | 74ABT2240D,112 | ABT | 935204060112 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | TI: SN74ABT2240 | Standard End of Life. |
| 74ABT2240D | 74ABT2240D,118 | ABT | 935204060118 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | TI: SN74ABT2240 | Standard End of Life. |
| 74ABT2240N | 74ABT2240N,112 | ABT | 935203720112 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | TI: SN74ABT2240 | Standard End of Life. |
| 74ABT2240PW | 74ABT2240PW,112 | ABT | 935203710112 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | TI: SN74ABT2240 | Standard End of Life. |
| 74ABT2240PW | 74ABT2240PW,118 | ABT | 935203710118 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | TI: SN74ABT2240 | Standard End of Life. |
| 74ABT377AD | 74ABT377AD,112 | ABT | 935244020112 | Т | М | 2 | 30-Jun-11 | 31-Dec-11 | TI: SN74ABT377 | Limited Availability. |
| 74ABT377AD | 74ABT377AD,118 | ABT | 935244020118 | Т | М | 2 | 30-Jun-11 | 31-Dec-11 | TI: SN74ABT377 | Limited Availability. |
| 74ABT377ADB | 74ABT377ADB,112 | ABT | 935244030112 | Т | М | 2 | 30-Jun-11 | 31-Dec-11 | TI: SN74ABT377 | Limited Availability. |
| 74ABT377ADB | 74ABT377ADB,118 | ABT | 935244030118 | Т | М | 2 | 30-Jun-11 | 31-Dec-11 | TI: SN74ABT377 | Limited Availability. |
| 74ABT377AN | 74ABT377AN,112 | ABT | 935244050112 | Т | М | 2 | 30-Jun-11 | 31-Dec-11 | TI: SN74ABT377 | Limited Availability. |
| 74ABT377APW | 74ABT377APW,112 | ABT | 935244040112 | Т | М | 2 | 30-Jun-11 | 31-Dec-11 | TI: SN74ABT377 | Limited Availability. |
| 74ABT377APW | 74ABT377APW,118 | ABT | 935244040118 | Т | М | 2 | 30-Jun-11 | 31-Dec-11 | TI: SN74ABT377 | Limited Availability. |
| BAP55L | | PINDIODE | 934058521315 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | BAP55LX | Standard End of Life. |
| BAS21J/DG | | SWITCHING DIODE | 934062288115 | N | М | 3 | 30-Jun-11 | 31-Dec-11 | BAS21J | Standard End Of Life. |
| BAS32L/R | | Switching diode | 934062229115 | N | М | 3 | 30-Jun-11 | 31-Dec-11 | BAS32L | Standard End Of Life. |
| BAS32L/R | | Switching diode | 934062229135 | N | М | 3 | 30-Jun-11 | 31-Dec-11 | BAS32L | Standard End Of Life. |
| BAS70-06W/DG | | Schottky diode | 934061852115 | N | М | 3 | 30-Jun-11 | 31-Dec-11 | BAS70-06W | Standard End Of Life. |
| BAT54A/DG | | Schottky diode | 934061179215 | N | М | 3 | 30-Jun-11 | 31-Dec-11 | BAT54A | Standard End Of Life. |
| BAT760/DG | | Schottky diode | 934061935115 | N | М | 3 | 30-Jun-11 | 31-Dec-11 | BAT760 | Standard End Of Life. |
| BAV103/R | | Switching diode | 934062228115 | N | М | 3 | 30-Jun-11 | 31-Dec-11 | BAV103 | Standard End Of Life. |
| BAV103/R | | Switching diode | 934062228135 | N | М | 3 | 30-Jun-11 | 31-Dec-11 | BAV103 | Standard End Of Life. |
| BAV70/DG | | Switching diode | 934062748215 | N | М | 3 | 30-Jun-11 | 31-Dec-11 | BAV70 | Standard End Of Life. |
| BAV70T/DG | | Switching diode | 934061911115 | N | М | 3 | 30-Jun-11 | 31-Dec-11 | BAV70T | Standard End Of Life. |
| BAV70W/DG | | Switching diode | 934061182115 | N | М | 3 | 30-Jun-11 | 31-Dec-11 | BAV70W | Standard End Of Life. |
| BAV70W/DG | | Switching diode | 934061182135 | N | М | 3 | 30-Jun-11 | 31-Dec-11 | BAV70W | Standard End Of Life. |
| BAW56/DG | | Switching diode | 934062749215 | N | М | 3 | 30-Jun-11 | 31-Dec-11 | BAW56 | Standard End Of Life. |
| BGE788 | BGE788,112 | CATV amplifier module | 934051200112 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | BGE788C | Standard End of Life. |
| BLF3G22-30 | BLF3G22-30,112 | BASESTATION RF POWER TTOR 2GHZ | 934057338112 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | BLF6G22-45 | Standard End of Life. |
| BLF3G22-30 | BLF3G22-30,135 | BASESTATION RF POWER TTOR 2GHZ | 934057338135 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | BLF6G22-45 | Standard End of Life. |
| BSH112 | BSH112,235 | 60V N TRENCHFET | 934056035235 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | 2N7002K or 2N7002BK | Standard End of Life. |
| BUK108-50DL | BUK108-50DL.118 | PowerMOS transistor | 934041700118 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard Availability. No Replacement Part. |

| BUK114-50L | BUK114-50L,118 | Logic level TOPFET | 934045690118 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard Availability. No Replacement Part. |
|--------------------|---------------------|--------------------------|--------------|----------|-----|---|------------------------|------------------------|----------------|---|
| BUK127-50GT | BUK127-50GT,115 | TOPFET | 934056898115 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard Availability. No Replacement Part. |
| BUK129-50DL | BUK129-50DL,118 | TOPFET | 934056336118 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | None noted | Standard Availability. No Replacement Part. |
| BUK129-50DL/C | 561126 6652,116 | TOPFET | 934060716118 | T | C | 3 | 30-Sep-11 | 31-Dec-11 | None | Standard Availability. No Replacement Part. |
| BUK129-50DL/C1 | | TOPFET | 934064406118 | T | C | 3 | 30-Sep-11 | 31-Dec-11 | None | Standard Availability. No Replacement Part. |
| BUK139-50DL/C1 | | TOPFET | 934061627118 | T | C | 2 | 30-Jun-11 | 31-Dec-11 | None | Limited Availability. |
| BUK1M200-50SGTD | | TOPFET | 934057351518 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard Availability. No Replacement Part. |
| BUK205-50Y | BUK205-50Y,118 | TOPFET, high side switch | 934041650118 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard Availability. No Replacement Part. |
| BUK213-50Y | BUK213-50Y,118 | MISC TOPFET2 | 934056316118 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard Availability. No Replacement Part. |
| BUK215-50Y | BUK215-50Y,118 | 9648 | 934055401118 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard Availability. No Replacement Part. |
| BUK218-50DC | BUK218-50DC,118 | TOPFET | 934056877118 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard Availability. No Replacement Part. |
| GTL2009PW | GTL2009PW,112 | GTL2009 | 935278365112 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard End of Life. |
| GTL2009PW | GTL2009PW,118 | GTL2009 | 935278365118 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard End of Life. |
| HSTL16918DGG | HSTL16918DGG,112 | HSTL16919 | 935270253112 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard End of Life. |
| HSTL16918DGG | HSTL16918DGG,118 | HSTL16919 | 935270253118 | т Т | M | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard End of Life. |
| 174F109D | 174F109D,602 | FAST LOGIC | 935032350602 | T | S | 3 | 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
| 174F109D | I74F109D,623 | FAST LOGIC | 935032350623 | T | S | 3 | 30-Sep-11 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
| 174F109D | 174F109D,623 | FAST LOGIC | 935032360602 | т Т | S | 3 | 30-Sep-11 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
| ICM7555IN/01 | ICM7555IN/01,112 | LINEAR INDUSTRIAL | 935274827112 | <u> </u> | M | 3 | 30-Sep-11 30-Jun-11 | 31-Dec-11 31-Dec-11 | ICM7555ID/01 | Standard End of Life. Standard Availability. Dip package discontinuation only. |
| 10101/0555110/01 | ICIVI7555IIN/01,112 | LINEAR INDUSTRIAL | 933274627112 | 1 | IVI | 3 | 30-Jun-11 | 31-Dec-11 | ICINI7555ID/01 | Standard Availability. Dip package discontinuation only. |
| J2A040CX0/T0BCA15 | | JCOP | 935293084118 | N | S | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |
| J2A080CX0/T0BCA16 | | JCOP | 935293075118 | N | S | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |
| J3A040CA4/T0BCAA90 | | JCOP | 935293086118 | N | S | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |
| J3A040YX0/T0BY1320 | | JCOP | 935292619118 | Ν | S | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |
| J3A080CA4/T0BC3430 | | JCOP | 935287317118 | Ν | с | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |
| J3A080CA4/T0BCAB10 | | JCOP | 935293067118 | Ν | s | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |
| J3A080CA4/T0BCAB61 | | JCOP | 935293455118 | Ν | s | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |
| J3A080CAI/T0BC1340 | | JCOP | 935286905699 | Ν | S | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |
| J3A080CAI/T0BC1370 | | JCOP | 935287231699 | Ν | с | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |
| J3A080GA4/T0BG1620 | | JCOP | 935288992118 | Ν | с | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |
| J3A080GX0/T0BG1330 | | JCOP | 935286906118 | Ν | s | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |
| J5A080GHN/T0BG1054 | | JCOP | 935291654151 | Ν | s | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |
| J5A080GHN/T0BG1054 | | JCOP | 935291654157 | N | S | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |

| | | | | | | | | | | Limited Availability. Outdated Software; Successor available on |
|--------------------|------------------------|-----------------------|--------------|---|---|---|-----------|-----------|--------------------|--|
| J5A080NUA/T0BG1974 | | JCOP | 935292462005 | N | S | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | JCOP v2.4.1 R3. Contact your local NXP sales office. |
| LPC2221FET64/01 | | 32-BIT ARM7 | 935283582118 | Т | С | 1 | 15-Dec-10 | 15-Dec-10 | None | Non-Manufacturable. |
| LPC2880FET180 | LPC2880FET180,551 | 32-BIT ARM7 HS USB | 935281368551 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | LPC1800 family | Standard End of Life. |
| LPC2888FET180/01 | LPC2888FET180/01,551 | 32-BIT ARM7 HS USB | 935285336551 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | LPC1800 family | Standard End of Life. |
| LPC2888FET180/D1 | LPC2888FET180/D1,551 | 32-BIT ARM7 HS USB | 935285219551 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | LPC1800 family | Standard End of Life. |
| LPC3220FET296 | LPC3220FET296,551 | 32-BIT ARM9 | 935287083551 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | LPC3220FET296/01 | Standard End of Life. |
| LPC3230FET296 | LPC3230FET296,551 | 32-BIT ARM9 | 935287119551 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | LPC3230FET296/01 | Standard End of Life. |
| LPC3240FET296 | LPC3240FET296,551 | 32-BIT ARM9 | 935286984551 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | LPC3240FET296/01 | Standard End of Life. |
| LPC3250FET296 | LPC3250FET296,551 | 32-BIT ARM9 | 935287084551 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | LPC3250FET296/01 | Standard End of Life. |
| LT1DC36C10/D | | T&L - CUSTOM SPECIFIC | 935273209118 | Т | М | 1 | 15-Dec-10 | 15-Dec-10 | LT5DC37C11/D | Non-Manufacturable. Contact your local NXP sales office |
| LT4DC36C10/D | | CUSTOM SPECIFIC | 935282663118 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | LT5DC37C10/D | Standard End Of Life. Contact your local NXP sales office. |
| LT4DC36C11/D | | CUSTOM SPECIFIC | 935282664118 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | LT5DC37C11/D | Standard End Of Life. Contact your local NXP sales office. |
| MF0ICU0101DUD | | CLHW | 935288382005 | N | М | 3 | 30-Jun-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| MF0ICU1021W/S7DL | | CLHW | 935290285005 | N | М | 3 | 30-Jun-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| MF0ICU1031W/S7DL | | CLHW | 935290286005 | N | М | 3 | 30-Jun-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| MF0ICU1501DUD | | CLHW | 935288385005 | N | М | 3 | 30-Jun-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| MF0MOU1501DA4 | | CLHW | 935288384118 | N | М | 3 | 30-Jun-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| MF0MOU1601DA4 | | CLHW | 935288386118 | N | М | 3 | 30-Jun-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| MF1ICS5005W/S7D | MF1ICS5005W/S7D,005 | CLHW | 935290544005 | т | м | 2 | 30-Jun-11 | 31-Dec-11 | See Comments | Limited Availability. UID Type. Will be replaced by next generation MIFARE Classic type from Q2 2011 onwards. Contact your local NXP sales office. |
| MF1PLUS6001DA4/02 | MF1PLUS6001DA4/02,118 | CLHW | 935289639118 | Ν | М | 1 | 15-Dec-10 | 15-Dec-10 | MF1PLUS6001DA4/03 | Non-Manufacturable. All deliveries of MIFARE Plus are transferred to the new version 3 silicon. Contact your local NXP sales office. |
| MF1PLUS6001DA4/12 | | CLHW | 935289641118 | N | м | 1 | 15-Dec-10 | 15-Dec-10 | MF1PLUS6001DA4/13 | Non-Manufacturable. All deliveries of MIFARE Plus are transferred to the new version 3 silicon. Contact your local NXP sales office. |
| MF1PLUS6021DA4/02 | | CLHW | 935289643118 | т | м | 1 | 15-Dec-10 | 15-Dec-10 | MF1PLUS6031DA4/03 | Non-Manufacturable. All deliveries of MIFARE Plus are transferred to the new version 3 silicon. Contact your local NXP sales office. |
| MF1PLUS6021DA4/02 | | CLHW | 935290204118 | т | M | 3 | 30-Jun-11 | 31-Dec-11 | MF1PLUS6031DA4/03 | Standard Availability. Contact your local NXP sales office. |
| MF1PLUS6021DUD/03 | | CLHW | 935290176005 | Т | M | 3 | 30-Jun-11 | 31-Dec-11 | MF1PLUS6031DUD/03 | Standard Availability. Contact your local NXP sales office. |
| MF1PLUS8001DA4/02 | MF1PLUS8001DA4/02,118 | CLHW | 935289644118 | N | M | 1 | 15-Dec-10 | 15-Dec-10 | MF1PLUS8001DA4/03 | Non-Manufacturable. All deliveries of MIFARE Plus are transferred to the new version 3 silicon. Contact your local NXP sales office. |
| MF1PLUS8001DA4/12 | | CLHW | 935289645118 | Ν | м | 1 | 15-Dec-10 | 15-Dec-10 | MF1PLUS8001DA4/13 | Non-Manufacturable. All deliveries of MIFARE Plus are transferred to the new version 3 silicon. Contact your local NXP sales office. |
| MF1PLUS8021DA4/02 | | CLHW | 935289637118 | т | м | 1 | 15-Dec-10 | 15-Dec-10 | MF1PLUS8031DA4/03 | Non-Manufacturable. All deliveries of MIFARE Plus are transferred to the new version 3 silicon. Contact your local NXP sales office. |
| MF1PLUS8021DA4/03 | | CLHW | 935290205118 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | MF1PLUS8031DA4/03 | Standard Availability. Contact your local NXP sales office. |
| MF1PLUS8021DUD/03 | | CLHW | 935290181005 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | MF1PLUS8031DUD/03 | Standard Availability. Contact your local NXP sales office. |
| MF1SPLUS6001DA4/02 | MF1SPLUS6001DA4/02,118 | CLHW | 935289632118 | Ν | М | 1 | 15-Dec-10 | 15-Dec-10 | MF1SPLUS6001DA4/03 | Non-Manufacturable. All deliveries of MIFARE Plus are transferred to the new version 3 silicon. Contact your local NXP sales office. |
| MF1SPLUS6021DA4/02 | | CLHW | 935289634118 | т | м | 1 | 15-Dec-10 | 15-Dec-10 | MF1SPLUS6031DA4/03 | Non-Manufacturable. All deliveries of MIFARE Plus are transferred to the new version 3 silicon. Contact your local NXP sales office. |
| MF1SPLUS6021DA4/03 | | CLHW | 935290197118 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | MF1SPLUS6031DA4/03 | Standard Availability. Contact your local NXP sales office. |
| MF1SPLUS6021DUD/03 | | CLHW | 935290172005 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | MF1SPLUS6031DUD/03 | Standard Availability. Contact your local NXP sales office. |
| MF1SPLUS8001DA4/02 | MF1SPLUS8001DA4/02,118 | CLHW | 935289635118 | Ν | М | 2 | 30-Jun-11 | 31-Dec-11 | | Limited Availability. All deliveries of MIFARE Plus are transferred to the new version 3 silicon. Contact your local NXP sales office. |

| | | | | | | | 1 | | | |
|---------------------|---------------|-------------------------|--------------|----|-----|---|-----------|------------------------|--------------------|---|
| | | | | | | | | | | Non-Manufacturable. All deliveries of MIFARE Plus are transferred to the new version 3 silicon. Contact your local NXP |
| MF1SPLUS8021DA4/02 | | CLHW | 935289638118 | т | м | 1 | 15-Dec-10 | 15-Dec-10 | MF1SPLUS8031DA4/03 | sales office. |
| MF1SPLUS8021DA4/03 | | CLHW | 935290192118 | Т | M | 3 | 30-Jun-11 | 31-Dec-11 | MF1SPLUS8031DA4/03 | Standard Availability. Contact your local NXP sales office. |
| MF1SPLUS8021DUD/03 | | CLHW | 935290168005 | Т | M | 3 | 30-Jun-11 | 31-Dec-11 | MF1SPLUS8031DUD/03 | Standard Availability. Contact your local NXP sales office. |
| N74F109D | N74F109D,602 | FAST LOGIC | 933739430602 | Т | M | 3 | 30-Jun-11 | 31-Dec-11 | TI: SN74F109 | Standard End of Life. |
| N74F109D | N74F109D,623 | FAST LOGIC | 933739430623 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | TI: SN74F109 | Standard End of Life. |
| N74F109N | N74F109N,602 | FAST LOGIC | 933668150602 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | TI: SN74F109 | Standard End of Life. |
| N74F259D | N74F259D,602 | FAST LOGIC | 933779080602 | Т | M | 3 | 30-Jun-11 | 31-Dec-11 | TI: SN74F109 | Standard End of Life. |
| N74F259D | N74F259D,623 | FAST LOGIC | 933779080623 | T | S | 3 | 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
| N74F259N | N74F259N.602 | FAST LOGIC | 933731290602 | т | S | 3 | 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
| N74F3038D | N74F3038D,512 | FAST LOGIC | 935008190512 | T | S | 3 | 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
| N74F3038D | N74F3038D,518 | FAST LOGIC | 935008190518 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
| N74F3038N | N74F3038N,602 | FAST LOGIC | 933747080602 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
| OC1006 | | TRENCH 4 | 934062957127 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard Availability. No Replacement Part. |
| 001000 | | | 001002001121 | | | | oo our ri | 01 200 11 | | |
| OH421 | | ROTATIONAL SPEED SENSOR | 934060287115 | N | S | 2 | 31-Jan-11 | 31-Mar-11 | See Comments | Limited Availability. Customer ordered EOL stock. Agreed replacement types are OH44x. Contact Marketing. |
| OH423 | | ROTATIONAL SPEED SENSOR | 934060288115 | N | s | 2 | 31-Jan-11 | 31-Mar-11 | See Comments | Limited Availability. Customer ordered EOL stock. Agreed replacement types are OH44x. Contact Marketing. |
| OM7670 | OM7670,112 | PUSH PULL | 934059925112 | Т | M | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard End of Life. |
| P3SR008A6/T0CM410 | 0111010,112 | CLHW | 935288357118 | N | M | 3 | 30-Jun-11 | 31-Dec-11 31-Dec-11 | See Comments | Standard End of Life. Standard End Of Life. Contact your local NXP sales office. |
| F33R008A0/10CIVI410 | | CENW | 935200357110 | IN | IVI | 3 | 30-301-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local tixer sales once. |
| P510U010V0/T2AV4J6 | | JCOP | 935286027118 | N | s | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |
| P521C072V0/T0PC026 | | JCOP | 935288724118 | N | С | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |
| P521G072V0/T0PG122 | | 08BIT CC | 935285515118 | Ν | S | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |
| P521G072W1/T0PG123 | | JCOP | 935285701005 | N | s | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |
| P521M018V0/T1DM515 | | JCOP | 935291015118 | Ν | s | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |
| P521M036V0/T1DM535 | | JCOP | 935291017118 | N | s | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |
| P530U012V4/T2BV3J71 | | JCOP | 935286962118 | N | s | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |
| P531C036V0/T0PC2180 | | JCOP | 935288861118 | N | С | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |
| P531C036W1/T0PC7591 | | 08BIT DIF | 935291072005 | Ν | с | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |
| P531G036W1/T0PB1230 | | 08BIT CC | 935282166005 | Ν | S | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |
| P531G072V4/T0QB1530 | | 08BIT DIF | 935284134118 | Ν | с | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. Outdated Software; Successor available on JCOP v2.4.1 R3. Contact your local NXP sales office. |
| P531G072VH/T0PB1610 | | JCOP | 935285328118 | Ν | с | 1 | 15-Dec-10 | 15-Dec-10 | See Comments | Non-Manufacturable. Outdated Software; Successor available on JCOP v2.4.1 R3; please contact your local NXP sales office |

| | | | | | | | | | Limited Availability. Outdated Software; Successor available on |
|--|----------------------|------------------------------|--------|--------|---|------------------------|------------------------|------------------------------|--|
| P531K072V0/T0PK3821 | JCOP | 935288523118 | Ν | С | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | JCOP v2.4.1 R3. Contact your local NXP sales office. |
| | | | | | | | | | |
| | 1000 | | | | | | | | Limited Availability. Outdated Software; Successor available on |
| P531M036V0/T0SM2801 | JCOP | 935289846118 | N | S | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | JCOP v2.4.1 R3. Contact your local NXP sales office. |
| P541G072TS/T0SG4754 | 08BIT TIF | 935289371112 | Ν | s | 2 | 30-Sep-11 | 04 Dec 44 | 0 | Limited Availability. USB devices no longer supported. Contact you local NXP sales office. |
| P541G07215/105G4754 | U8BIT TIF | 935289371112 | N | 5 | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | |
| P541G072TS/T0SG4781 | 08BIT TIF | 935289372112 | Ν | s | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | Limited Availability. USB devices no longer supported. Contact vou local NXP sales office. |
| 1341007210/10004701 | | 333203372112 | IN IN | 5 | 2 | 30-0ep-11 | 31-060-11 | See Comments | Limited Availability. USB devices no longer supported. Contact |
| P541G072V0/T0SG4761 | 08BIT TIF | 935289368118 | Ν | s | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | you local NXP sales office. |
| | | | | - | | | | | Limited Availability. USB devices no longer supported. Contact |
| P541G072V0/T0SG4770 | 08BIT TIF | 935289369118 | Ν | S | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | you local NXP sales office. |
| | | | | | | | | | Limited Availability. USB devices no longer supported. Contact |
| P541G072V0/T0SG4794 | 08BIT TIF | 935289367118 | Ν | S | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | you local NXP sales office. |
| | | | | | | | | | Limited Availability. USB devices no longer supported. Contact |
| P541G072W1/T0SG4800 | 08BIT CC | 935290679005 | N | S | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | you local NXP sales office. |
| | | | | | | | | | Limited Availability. USB devices no longer supported. Contact |
| P541G072W1/T0SG4811 | 08BIT CC | 935291294005 | Ν | S | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | you local NXP sales office. |
| | | | | | | | | | Limited Availability. USB devices no longer supported. Contact |
| P541G072W1/T0SG4A44 | 08BIT CC | 935290666005 | N | S | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | you local NXP sales office. |
| P5CC008UA/T0A012B | 08BIT CC | 935288594005 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CC009EV0/T2A3136 | 08BIT CC | 935288358118 | Т | C C | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CC009EV0/T2A3339 P5CC009EW1/T1D4108 | 08BIT CC 08BIT CC | 935289307118 935278525005 | т N | C C | 3 | 30-Sep-11 30-Sep-11 | 31-Dec-11 31-Dec-11 | See Comments See Comments | Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. |
| P5CC009EW1/T1D4108 | 08BIT CC | 935278525005 | N | c | 3 | 30-Sep-11 30-Sep-11 | 31-Dec-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. |
| P5CC009EW1/T1D4521 | 08BIT CC | 935287989005 | N | c | 3 | 30-Sep-11 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CC009EW1/T1D4530 | 08BIT CC | 935286143005 | N | c | 3 | 30-Sep-11 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CC009EW1/T1D4531 | 08BIT CC | 935286565005 | N | c | 3 | 30-Sep-11 | 31-Dec-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CC009EW1/T1D4534 | 08BIT CC | 935287352005 | N | c | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CC009EW1/T1D4535 | 08BIT CC | 935287471005 | N | C | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CC009EW1/T1D4536 | 08BIT CC | 935287608005 | N | C | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CC009EW1/T1D4537 | 08BIT CC | 935288474005 | N | C | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CC009EW1/T1D4538 | 08BIT CC | 935289051005 | N | C | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CC009EW1/T1D5305 | 08BIT CC | 935282315005 | N | C | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CC024UA/T0A0403 | 08BIT CC | 935287946005 | N | C | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CC036EV0/T1D4314 | 08BIT CC | 935279654118 | Т | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CC036EW1/T1D4314 | 08BIT CC | 935281928005 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CC037UA/T0A023A | 08BIT CC | 935285457005 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CC037UA/T0A023B | 08BIT CC | 935285458005 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CC037UA/T0AFF02 | 08BIT CC | 935284141005 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| | | | | | | | | | |
| | | | | | | | | | Limited Availability. Outdated Software: Successor available on |
| P5CC037XS/T0AG001 | 08BIT CC | 935284129118 | Ν | S | 2 | 30-Sep-11 | 31-Dec-11 | See Comments | JCOP v2.4.1 R3. Contact your local NXP sales office. |
| P5CC040XS/T0B0401 | 08BIT CC | 935283332118 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CC052XS/T0A0404 | 08BIT CC | 935286013118 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CC073HN/T0B1301 | 08BIT CC | 935286488118 | Ν | S | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CC073UA/T0B4406 | 08BIT CC | 935288784005 | Ν | S | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CC073XI/T0B1301 | 08BIT CC | 935288974118 | Т | С | 2 | 28-Feb-11 | 30-Jun-11 | See Comments | Limited Availability. Contact your local NXP sales office. |
| P5CC080UA/T0B4705 | 08BIT CC | 935288937005 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CC080XS/T0B2702 | 08BIT CC | 935288305118 | Ν | S | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CD012UA/T0B24061 | 08BIT DIF | 935287586005 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CD012UA/T0B28111 | 08BIT DIF | 935288064005 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CD036EV4/T0QF7411 | 08BIT DIF | 935289697118 | Ν | S | 3 | 30-Sep-11 | 31-Dec-11 | P5CD040 | Standard End Of Life. Contact your local NXP sales office. |
| P5CD040A4/T0B25151 | 08BIT DIF | 935289698118 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CD040A4/T0B34050 | 08BIT DIF | 935288854118 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CD040X0/T0B22144 | 08BIT DIF | 935287398118 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |

| P5CD072EW1/T0PE8780 | | 08BIT DIF | 935283413005 | N | S | 3 | 30-Sep-11 31-Dec-11 | P5CD081 | Standard End Of Life. Contact your local NXP sales office. |
|--|-----------------|-------------------------------|--------------|---|---|---|---------------------|---------------|--|
| P5CD072EW1/T0SFAG41 | | 08BIT DIF | 935289431005 | N | s | 3 | 30-Sep-11 31-Dec-11 | P5CD081 | Standard End Of Life. Contact your local NXP sales office. |
| P5CD080A4/T0B20220 | | 08BIT DIF | 935289431003 | N | S | 3 | 30-Sep-11 31-Dec-11 | P5CD081 | Standard End Of Life. Contact your local NXP sales office. |
| P5CD080A4/T0B20220 | | 08BIT DIF | | | C | 3 | | | , |
| | | | 935288845118 | N | | - | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CD080UA/T0B07010 | | 08BIT DIF | 935283589005 | N | S | 3 | 30-Sep-11 31-Dec-11 | See comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CD080UA/T0B12A11 | | 08BIT DIF | 935288125005 | N | S | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CD080UA/T0B35474 | | 08BIT DIF | 935287817005 | N | С | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CD080UA/T0B35484 | | 08BIT DIF | 935287995005 | N | С | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CD080UA/T0B44491 | | 08BIT DIF | 935288782005 | N | S | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CD080UE/T0B20300 | | 08BIT DIF | 935287799005 | N | S | 3 | 30-Sep-11 31-Dec-11 | P5CD081 | Standard End Of Life. Contact your local NXP sales office. |
| P5CD080X0/T0B35544 | | 08BIT DIF | 935288184118 | N | С | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CD080X0/T0B37381 | | 08BIT DIF | 935288083118 | N | С | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CD080XI/T0B07010 | | 08BIT DIF | 935289761118 | Т | С | 2 | 28-Feb-11 30-Jun-11 | See Comments | Limited Availability. Contact your local NXP sales office. |
| P5CD081UA/T1A2414 | | 08BIT DIF | 935289337005 | N | S | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CD081UA/T1A2515 | | 08BIT DIF | 935289331005 | N | S | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CD144A4/T0B23140 | | 08BIT DIF | 935286052118 | N | S | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CD144UA/T0B19130 | | 08BIT DIF | 935288878005 | N | С | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CD144UA/T0B34171 | | 08BIT DIF | 935288774005 | N | S | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CD144UE/T0B07030 | | 08BIT DIF | 935287377005 | N | С | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CD144XI/T0B07030 | | 08BIT DIF | 935289767118 | т | С | 2 | 28-Feb-11 30-Jun-11 | See Comments | Limited Availability. Contact your local NXP sales office. |
| P5CD144XI/T0B32211 | | 08BIT DIF | 935291548118 | T | C | 2 | 28-Feb-11 30-Jun-11 | See Comments | Limited Availability. Contact your local NXP sales office. |
| P5CT072ETS/T0PBG350 | | 08BIT TIF | 935283897112 | T | S | 3 | 30-Sep-11 31-Dec-11 | P5CD081 | Standard End Of Life. Contact your local NXP sales office. |
| P5CT072ETS/T0PE8870 | | 08BIT TIF | 935283575118 | T | S | 3 | 30-Sep-11 31-Dec-11 | P5CD081 | Standard End Of Life. Contact your local NXP sales office. |
| P5CT072EV0/T0PBG350 | | 08BIT TIF | 935283569118 | T | S | 3 | 30-Sep-11 31-Dec-11 | P5CD081 | Standard End Of Life. Contact your local NXP sales office. |
| P5CT072EV4/T0QB6311 | | 08 BIT TIF | 935285233118 | Т | S | 3 | 30-Sep-11 31-Dec-11 | P5CD081 | Standard End Of Life. Contact your local NXP sales office. |
| | | | | N | S | - | | | · · · |
| P5CT072EV7/T0PBT620 | | 08BIT TIF | 935282954118 | N | | 3 | 30-Sep-11 31-Dec-11 | P5CD081 | Standard End Of Life. Contact your local NXP sales office. |
| P5CT072EW1/T0PBG350 | | | 935281673005 | | S | 3 | 30-Sep-11 31-Dec-11 | P5CD081 | Standard End Of Life. Contact your local NXP sales office. |
| P5CT072EW1/T0PBT630 | | 08BIT TIF | 935282163005 | N | S | 3 | 30-Sep-11 31-Dec-11 | P5CD081 | Standard End Of Life. Contact your local NXP sales office. |
| P5CT072EW1/T0PE8870 | | 08BIT TIF | 935283412005 | N | S | 3 | 30-Sep-11 31-Dec-11 | P5CD081 | Standard End Of Life. Contact your local NXP sales office. |
| P5CT072EW1/T0PF2U61 | | 08BIT TIF | 935286219005 | N | С | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CT072EW1/T0PF8661 | | 08BIT TIF | 935287607005 | N | S | 3 | 30-Sep-11 31-Dec-11 | P5CD081 | Standard End Of Life. Contact your local NXP sales office. |
| P5CT072EW8/T0PF8661 | | 08BIT TIF | 935287598005 | Т | S | 3 | 30-Sep-11 31-Dec-11 | P5CD081 | Standard End Of Life. Contact your local NXP sales office. |
| P5CT072EWH/T0PE8870 | | 08BIT TIF | 935288309005 | Т | S | 3 | 30-Sep-11 31-Dec-11 | P5CD081 | Standard End Of Life. Contact your local NXP sales office. |
| P5CU036ETS/T0PET03 | | 08BIT CC | 935287539118 | Т | С | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CU036ETS/T0PEZ05 | | 08BIT CC | 935287538118 | Т | С | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5CU036EW1/T0PEZ05 | | 08BIT CC | 935286137005 | Т | С | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5SD009EV0/T2A18010 | | 08BIT DIF | 935283304118 | N | С | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5SD009EV0/T2A28064 | | 08BIT DIF | 935286459118 | N | С | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5SD009EV3/T2A18010 | | 08BIT DIF | 935283312118 | N | С | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P5SD009EW1/T2A21031 | | 08BIT DIF | 935286272005 | N | С | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P7CC145EW1/T0F2007 | | 16BIT SXA | 935281915005 | N | С | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P7SC145EW1/T0F14A3 | | 16 BIT SXA | 935280801005 | N | С | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P87C51FA-5B | | 51 FAMILY OTP/EPROM - 87C51FA | 935253980557 | Т | S | 3 | 30-Sep-11 31-Dec-11 | None noted | Standard End of Life. |
| P8WE5008AEW/00305W | | 08BIT CC | 935273268005 | Т | S | 3 | 30-Sep-11 31-Dec-11 | P5CC008 | Standard End Of Life. Contact your local NXP sales office. |
| P8WE5017AEW/01715W | | 08BIT CC | 935272942005 | Т | S | 3 | 30-Sep-11 31-Dec-11 | P5CC018 | Standard End Of Life. Contact your local NXP sales office. |
| P8WE5032AEW/02411W | | 08BIT SC | 935268008005 | T | S | 3 | 30-Sep-11 31-Dec-11 | P5CC037 | Standard End Of Life. Contact your local NXP sales office. |
| P8WE5032AEW/03403W | | 08BIT SC | 935269975005 | T | M | 3 | 30-Jun-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P8WE5032AEW/06911W | | 08BIT SC | 935293571005 | T | S | 3 | 30-Sep-11 31-Dec-11 | P5CC037 | Standard End Of Life. Contact your local NXP sales office. |
| P8WE5033AEW/037A4W | | 08BIT CC | 935273345005 | T | c | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P8WE6004AEW/00504W | | 08BIT SC | 935270236005 | Т | M | 3 | 30-Jun-11 31-Dec-11 | | Standard End Of Life. Contact your local NXP sales office. |
| P8WE6004AEW/00504W P8WE6004AEW/008A9W | | 08BIT SC | | Т | C | 3 | | See Comments | Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. |
| | | | 935271027005 | | | ÷ | 30-Sep-11 31-Dec-11 | See Comments | |
| P8WE6004AEW/02412W | | 08BIT SC | 935289074005 | Т | С | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P8WE6008AEW/10709W | | 08BIT SC | 935270237005 | Т | M | 3 | 30-Jun-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P8WE6017AEW/13225W | | 08BIT SC | 935271019005 | Т | С | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P8WE6017AEW/143B5W | | 08BIT SC | 935280377005 | Т | С | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| P8WE6017AEW/143G6W | | 08BIT SC | 935279738005 | Т | С | 3 | 30-Sep-11 31-Dec-11 | See Comments | Standard End Of Life. Contact your local NXP sales office. |
| PCA82C250T/YMX | | AUTOMOTIVE NIJMEGEN | 935293868118 | N | S | 1 | 15-Dec-10 15-Dec-10 | PCA82C250T/YM | Non-Manufacturable. |
| PCA9504ADGG | PCA9504ADGG,112 | GLUE CHIP 4 REV A | 935267864112 | Т | М | 2 | 30-Jun-11 31-Dec-11 | None | Limited Availability. |
| | | | | | | | | | |

| PCA9504ADGG | PCA9504ADGG,118 | GLUE CHIP 4 REV A | 935267864118 | т | М | 2 | 30-Jun-11 | 31-Dec-11 | None | Limited Availability. |
|--------------------------------------|------------------------|--------------------------|--------------|---|---|---|-----------|-----------|--------------------|--|
| PCA9549BS | PCA9549BS,118 | PCA9549 | 935282228118 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None | Standard End of Life. |
| PCA9549D | PCA9549D,112 | PCA9549 | 935282229112 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None | Standard End of Life. |
| PCA9549D | PCA9549D,118 | PCA9549 | 935282229118 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None | Standard End of Life. |
| | | | | | | | | | | |
| PCA9549PW | PCA9549PW,112 | PCA9549 | 935282231112 | т | S | 3 | 30-Sep-11 | 31-Dec-11 | None | Standard End of Life. |
| | | | | | | | | | | |
| PCA9549PW | PCA9549PW,118 | PCA9549 | 935282231118 | т | S | 3 | 30-Sep-11 | 31-Dec-11 | None | Standard End of Life. |
| | | | | | | | | | | Standard End Of Life. Refer to PCN 201008012. Contact |
| PCF7321ATS/B07A2 | | PKE CHIPS | 935275216118 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| PCF7321ATS/B1100 | | PKE CHIPS | 935276722118 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| PCF7321ATS/B1500 | | PKE CHIPS | 935282108118 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| | | | | | | | | | | |
| PCF7321ATS/B2505 | | PKE CHIPS | 935285331118 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | PCF7321ATS/M1AB45 | Standard End Of Life. Refer to PCN 201008012. |
| | | | | | | | | | | |
| PCF7321ATS/C1AB3307 | | PKE CHIPS | 935288671518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | PCF7321ATS/M1AB337 | Standard End Of Life. Refer to PCN 201008012. |
| | | | | | | | | | | Standard End Of Life. Refer to PCN 201008012. Contact |
| PCF7321ATT/B2906 | | PKE CHIPS | 935287547518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| | | | | | | | | | | Standard End Of Life. Refer to PCN 201008012. Contact |
| PCF7321ATT/B3500 | | PKE CHIPS | 935289776518 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| | | | | | | | | | | Standard End Of Life. Refer to PCN 201008012. Contact |
| PCF7341ATS/B08Z0 | | IMMO COMBI CHIP | 935275215118 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| | | | | | | | | | | Standard End Of Life. Refer to PCN 201008012. Contact |
| PCF7341ATS/B0901 | | IMMO COMBI CHIP | 935275336118 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| | | | | | | | | | | Standard End Of Life. Refer to PCN 201008012. Contact |
| PCF7341ATS/B1200 | | IMMO COMBI CHIP | 935277934118 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| | | | | | | | | | | Standard End Of Life. Refer to PCN 201008012. Contact |
| PCF7341ATS/B1323 | | IMMO COMBI CHIP | 935280556118 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| | | | | | | | | | | Standard End Of Life. Refer to PCN 201008012. Contact |
| PCF7341ATS/B14L2 | | IMMO COMBI CHIP | 935282005118 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| | | | | | | | | | | Standard End Of Life. Refer to PCN 201008012. Contact |
| PCF7341ATS/B1902 | | IMMO COMBI CHIP | 935283259118 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| | | | | | | | | | | Standard End Of Life. Refer to PCN 201008012. Contact |
| PCF7341ATS/B20S1 | | IMMO COMBI CHIP | 935284142118 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| | | | | | | | | | | Standard End Of Life. Refer to PCN 201008012. Contact |
| PCF7341ATT/B17D1 | | IMMO COMBI CHIP | 935282859518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| | | | | | | | | | | Standard End Of Life. Refer to PCN 201008012. Contact |
| PCF7341ATT/B23D4 | | IMMO COMBI CHIP | 935284731518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| | | | | | | | | | | Standard End Of Life. Refer to PCN 201008012. Contact |
| PCF7341ATT/B36D4 | | IMMO COMBI CHIP | 935289908518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| PCF7341ETT/C0AB2403 | | IMMO COMBI CHIP | 935285098518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| PCF7341ETT/C0AB27A3 | | IMMO COMBI CHIP | 935285584518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| PCF7345ATT/C0BC0300 | | IMMO COMBI CHIP | 935289781118 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | PCF7345ATT/MBC3 | Standard End of Life. Refer to PCN 201007003. |
| PCF7900NHN/C0G | | TRANSMITTER CHIPS | 935282251118 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Refer to PCN 201003010. |
| | | | | | | | | | | |
| PCF7900VHN/C0I | | TRANSMITTER CHIPS | 935282269118 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Refer to PCN 201003010. |
| PCF7921ATS/3391/2A | | KEYLESS ENTRY CONTROLLER | 935286728118 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | PCF7921ATS/M2AB12 | Standard End Of Life. Refer to PCN 201008012. |
| | | | | | | | | | | Standard End Of Life. Refer to PCN 201008012. Contact |
| PCF7921ATS/B1010 | | KEYLESS ENTRY CONTROLLER | 935288888118 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| | | | | | | | | | | |
| PCF7921ATT/3601/2A | PCF7921ATT/3601/2A,118 | KEYLESS ENTRY CONTROLLER | 935286483118 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | PCF7921ATT/M2AB12 | Standard End Of Life. Refer to PCN 201008012. |
| | | | | | | | | | | Standard End Of Life. Refer to PCN 201008012. Contact |
| PCF7922ATT/C0404 | | PKE CHIPS | 935280433518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| | | | | | | | | | | Standard End Of Life. Refer to PCN 201008012. Contact |
| | 1 | PKE CHIPS | 935281801518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| PCF7922ATT/C0606 | | | | | | | | | | |
| PCF7922ATT/C0606 PCF7922ATT/C0707 | | PKE CHIPS | 935282284518 | N | с | 3 | 30-Sep-11 | 31-Dec-11 | | Standard End Of Life. Refer to PCN 201008012. Contact Marketing for Replacement Part. |

| | 1 | 1 | - | | | | | | | |
|--|-------------------------|-----------------|--------------|---|--------|---|------------------------|------------------------|---------------------|--|
| PCF7922ATT/C0808 | | PKE CHIPS | 935283269518 | N | с | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Refer to PCN 201008012. Contact Marketing for Replacement Part. |
| PCF7922ATT/C0909 | | PKE CHIPS | 935286304518 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Refer to PCN 201008012. Contact Marketing for Replacement Part. |
| PCF7922ATT/C1010 | | PKE CHIPS | 935283408518 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Refer to PCN 201008012. Contact Marketing for Replacement Part. |
| PCF7922ATT/C1AE0700 | | PKE CHIPS | 935287313518 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | PCF7922ATT/M1AE7 | Standard End Of Life. Refer to PCN 201008012. |
| PCF7922ATT/C1AE0710 | | PKE CHIPS | 935293609518 | N | с | 1 | 15-Dec-10 | 15-Dec-10 | PCF7961ATT/M1AC719 | Non-Manufacturable. Refer to PCN PCN 201008012. Contact Marketing for Replacement Part. |
| PCF7922ATT/CV300 | | PKE CHIPS | 935282942518 | N | c | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Refer to PCN 201008012. Contact Marketing for Replacement Part. |
| | | | | | | | | | | Standard End Of Life. Refer to PCN 201008012. Contact |
| PCF7922ATT/CV404 | | PKE CHIPS | 935282945518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. Standard End Of Life. Refer to PCN 201008012. Contact |
| PCF7922ATT/E | | PKE CHIPS | 935278539512 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| PCF7922ATT/E | | PKE CHIPS | 935278539518 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| PCF7936AS/3851/A | | STICKS | 935290556122 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| PCF7941ATS/3391/2A | PCF7941ATS/3391/2A, 118 | COMBI CHIPS | 935286482118 | N | C | 3 | 30-Sep-11 | 31-Dec-11 | PCF7941ATS/M2AB12 | Standard End Of Life. Refer to PCN 201008012. |
| PCF7941ATT/3601/2A | PCF7941ATT/3601/2A,118 | | 935286481118 | N | C | 3 | 30-Sep-11 | 31-Dec-11 | PCF7941ATT/M2AB12 | Standard End Of Life. Refer to PCN 201008012. |
| PCF7941ETT/C2AB3000 | 1 0173417173001/27,110 | | 935288842118 | N | c | 3 | 30-Sep-11 30-Sep-11 | 31-Dec-11 | PCF7941ETT/M2AB3 | Standard End Of Life. Refer to PCN 201008012. |
| | | | | N | C C | - | | | | |
| PCF7945ATT/C0BC05 | | | 935281065518 | | | 3 | 30-Sep-11 | 31-Dec-11 | PCF7945ATT/MBC5 | Standard End of Life. Refer to PCN 201007003. |
| PCF7945ATT/C0BC06 | | IMMO | 935281085518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | PCF7945ATT/MBC6 | Standard End of Life. Refer to PCN 201007003. |
| PCF7945ATT/C0BC0603 | | IMMO | 935283216518 | Ν | с | 3 | 30-Sep-11 | 31-Dec-11 | PCF7945ATT/MBC63 | Standard End of Life. Refer to PCN 201007003. |
| PCF7945ATT/C0BC0609 | | IMMO | 935283428518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | PCF7945ATT/MBC69 | Standard End of Life. Refer to PCN 201007003. |
| PCF7945ATT/C0BC0910 | | IMMO | 935286404518 | N | C | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| PCF7945ATT/C1AC1411 | | IMMO | 935289784518 | N | c | 3 | 30-Sep-11 30-Sep-11 | 31-Dec-11 | PCF7945ATT/M1AC1411 | Standard End of Life. Refer to PCN 201007003. |
| PCF7945ATT/C1AC1411 PCF7945ATT/C1AC1500 | | IMMO | | N | c | 3 | • | | | |
| PCF7945ATT/C1AC1500 PCF7945ATT/C1AC1700 | | IMMO | 935289689518 | N | - | - | 30-Sep-11 | 31-Dec-11 | PCF7945ATT/M1AC15 | Standard End of Life. Refer to PCN 201007003. |
| PCF7945A11/C1AC1700 | | | 935289943518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | PCF7945ATT/M1AC17 | Standard End of Life. Refer to PCN 201007003. |
| PCF7945PTT/C0BC1200 | | ІММО СОМВІ СНІР | 935283939518 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | PCF7945PTT/MBC12 | Standard End of Life. Refer to PCN 201007003. |
| PCF7945PTT/C1AC1800 | | IMMO COMBI CHIP | 935289946518 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | PCF7945PTT/M1AC18 | Standard End of Life. Refer to PCN 201007003. |
| PCF7946AT/1081/C | | COMBI CHIPS | 935288835512 | N | s | 3 | 30-Sep-11 | 31-Dec-11 | PCF7946AT/181/CM | Standard End Of Life. Refer to CIN 200910033 as update to PCN 200901032. Contact Marketing for Replacement Part. |
| PCF7946AT/1081/C | | COMBI CHIPS | 935288835518 | Ν | S | 3 | 30-Sep-11 | 31-Dec-11 | PCF7946AT/181/CM | PCN 200901032. Contact Marketing for Replacement Part. |
| PCF7947AT/1081/C | | COMBI CHIPS | 935288839518 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | PCF7947AT/181/CM | PCN 200901032. Contact Marketing for Replacement Part. |
| PCF7952ATS/C1CC12 | | PKE CHIPS | 935286225118 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | PCF7952ATS/M1CC12 | Standard End Of Life. Refer to PCN 201008012. |
| PCF7952ATT/C1CC11 | | PKE CHIPS | 935286145118 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | PCF7952ATT/M1CC11 | Standard End Of Life. Refer to PCN 201008012. |
| PCF7952ATT/C1CC12 | | PKE CHIPS | 935286146118 | N | C | 3 | 30-Sep-11 | 31-Dec-11 | PCF7952ATT/M1CC12 | Standard End Of Life. Refer to PCN 201008012. |
| PCF7952ATT/C1CC15 | | PKE CHIPS | 935286144118 | N | C | 3 | 30-Sep-11 | 31-Dec-11 | PCF7952ATT/M1CC15 | Standard End Of Life. Refer to PCN 201008012. |
| PCF7952ETT/C1CC16 | | PKE CHIPS | 935288326118 | N | c | 3 | 30-Sep-11 30-Sep-11 | 31-Dec-11 | PCF7952ETT/M1CC16 | Standard End Of Life. Refer to PCN 201008012. |
| | | | 300200020110 | | 0 | 0 | 00 000 11 | 01 200 11 | | |
| PCF7952LTT/C1CC15 | | IMMO ACTIC | 935289783118 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | PCF7952LTT/M1CC15 | Standard End Of Life. Refer to PCN 201008012. |
| PCF7953ATT/C0BC05 | | PKE CHIPS | 935281062518 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | PCF7953ATT/MBC5 | Standard End of Life. Refer to PCN 201007003. |
| PCF7953ATT/C0BC06 | | PKE CHIPS | 935281084518 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| PCF7953ATT/C1AC1411 | | PKE CHIPS | 935287777518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | PCF7953ATT/M1AC1411 | Standard End of Life. Refer to PCN 201007003. |
| PCF7953ATT/C1AC1500 | | PKE CHIPS | 935287782512 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | PCF7953ATT/M1AC15 | Standard End of Life. Refer to PCN 201007003. |
| PCF7953ATT/C1AC1500 | | PKE CHIPS | 935287782518 | N | с | 3 | 30-Sep-11 | 31-Dec-11 | PCF7953ATT/M1AC15 | Standard End of Life. Refer to PCN 201007003. |
| PCF7953ATT/C1AC1700 | | PKE CHIPS | 935288667518 | N | C | 3 | 30-Sep-11 | 31-Dec-11 | PCF7953ATT/M1AC17 | Standard End of Life. Refer to PCN 201007003. |
| PCF7953ATT/CTAC1700 PCF7953ATT/M0BC05 | | PKE CHIPS | 935292766518 | N | C C | 3 | 30-Sep-11 30-Sep-11 | 31-Dec-11 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| | | | | | - | | - | | | |
| PCF7953PTT/C0BC1100 | | PKE CHIPS | 935284275518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | PCF7953PTT/MBC11 | Standard End of Life. Refer to PCN 201007003. |
| PCF7953PTT/C0BC1200 | | PKE CHIPS | 935283936518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | PCF7953PTT/MBC12 | Standard End of Life. Refer to PCN 201007003. |
| PCF7953PTT/C1AC1600 | | PKE CHIPS | 935288669518 | Ν | С | 3 | 30-Sep-11 | 31-Dec-11 | PCF7953PTT/M1AC16 | Standard End of Life. Refer to PCN 201007003. |

| i | | | | | | | 1 | 1 | r | |
|---------------------|----------------------|--------------------|--------------|---|---|---|-----------|-----------|-------------------|--|
| PCF7953PTT/C1AC1800 | | PKE CHIPS | 935288668518 | N | с | 3 | 30-Sep-11 | 31-Dec-11 | PCF7953PTT/M1AC18 | Standard End of Life. Refer to PCN 201007003. |
| PCF7953PTT/M0BC1100 | | PKE CHIPS | 935293054518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End of Life. Refer to PCN 201007003. Contact Marketing for Replacement Part. |
| PCF7953PTT/M0BC1200 | | PKE CHIPS | 935293053518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End of Life. Refer to PCN 201007003. Contact Marketing for Replacement Part. |
| PCF7961ATT/B1212C | | COMBI CHIPS | 935284687518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Refer to PCN 201008012. Contact Marketing for Replacement Part. |
| PCF7961ATT/B1313E | | COMBI CHIPS | 935285006518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Refer to PCN 201008012. Contact Marketing for Replacement Part. |
| PCF7961ATT/B1414C | | COMBI CHIPS | 935287677518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Refer to PCN 201008012. Contact Marketing for Replacement Part. |
| PCF7961ATT/C00V1 | PCF7961ATT/C00V1,518 | COMBI CHIPS | 935279578518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| PCF7961ATT/C0101 | | COMBI CHIPS | 935284688518 | N | с | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Refer to PCN 201008012. Contact Marketing for Replacement Part. |
| PCF7961ATT/C1AC0700 | | COMBI CHIPS | 935290446518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | PCF7961ATT/M1AC7 | Standard End Of Life. Refer to PCN 201008012. |
| PCF7961ATT/C1AC0716 | | COMBI CHIPS | 935291811518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Refer to PCN 201008012. Contact Marketing for Replacement Part. |
| PCF7961ATT/C1AE0700 | | COMBI CHIPS | 935287312518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | PCF7961ATT/M1AE7 | Standard End Of Life. Refer to PCN 201008012. |
| PCF7961ATT/C1AE0719 | | COMBI CHIPS | 935293661518 | N | С | 1 | 15-Dec-10 | 15-Dec-10 | PCF7922ATT/M1AC71 | Non-Manufacturable. Refer to PCN PCN 201008012. Contact Marketing for Replacement Part. |
| PCF7961ATT/CV200 | | COMBI CHIPS | 935282037518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Refer to PCN 201008012. Contact Marketing for Replacement Part. |
| PCF7961ATT/E | | COMBI CHIPS | 935278538512 | N | с | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Refer to PCN 201008012. Contact Marketing for Replacement Part. |
| PCF7961ATT/E | PCF7961ATT/E,518 | COMBI CHIPS | 935278538518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| PCF7961ETT/E | | IMMO COMBI CHIP | 935285163518 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Marketing for Replacement Part. |
| PCF7991AT/1081 | PCF7991AT/1081,112 | READER CHIPS | 935260093112 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | PCF7991AT/181/M | Standard End Of Life. Refer to PCN 201008012. |
| PCF7991AT/1081 | PCF7991AT/1081,118 | READER CHIPS | 935260093118 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | PCF7991AT/181/M | Standard End Of Life. Refer to PCN 201008012. |
| PCF7991AT/1081 | | READER CHIPS | 935260093518 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | PCF7991AT/181/M | Standard End Of Life. Refer to PCN 201008012. |
| PCF8535U/2/F1 | PCF8535U/2/F1,026 | 65X133 B&W GRAPHIC | 935263718026 | т | м | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard End of Life. |
| PCF8576DH/2 | PCF8576DH/2,518 | LCD SEGMENT DRIVER | 935276165518 | т | s | 1 | 15-Dec-10 | 15-Dec-10 | PCF85176H/1 | Non-Manufacturable. |
| PCH7371AU/C0BXB19 | | ТРМ | 935282589025 | N | с | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End of Life. Contact Marketing for Replacement Part. |
| PCH7371AU/C0BXB20 | | ТРМ | 935282591025 | N | с | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End of Life. Contact Marketing for Replacement Part. |
| PCH7371AW/C0BXB08 | | TIRE PRESSURE MON | 935278718005 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End of Life. Contact Marketing for Replacement Part. |
| PCH7371AW/C0BXB13 | | TIRE PRESSURE MON | 935280233005 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End of Life. Contact Marketing for Replacement Part. |
| PCH7371AW/C0BXB21 | | TIRE PRESSURE MON | 935282702005 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End of Life. Contact Marketing for Replacement Part. |
| PCH7372AU/C0BXB12 | | ТРМ | 935282577025 | N | с | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End of Life. Contact Marketing for Replacement Part. |
| PCH7372AU/C0BXB21 | | ТРМ | 935282827025 | N | с | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End of Life. Contact Marketing for Replacement Part. |
| PCH7372AU/C0BXB22 | | ТРМ ТРМ | 935282829025 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End of Life. Contact Marketing for Replacement Part. |
| PCH7372AU/C0BXB23 | | | 935282838025 | N | C | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End of Life. Contact Marketing for Replacement Part. |
| PCH7372AW/C0BXB22 | | TIRE PRESSURE MON | 935282837005 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End of Life. Contact Marketing for Replacement Part. |
| PCH7900NTT/C0G | | TRANSMITTER CHIPS | 935282306118 | N | s | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Refer to PCN 201003010. |
| PCH7900VTT/C0I | | TRANSMITTER CHIPS | 935282305118 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End Of Life. Refer to PCN 201003010. |

| | | | 1 | | | | | | | |
|--|--|---|--|---|---|--|--|--|---|--|
| PCH7970AU/C0CXB04 | | ТРМ | 935282576025 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End of Life. Contact Marketing for Replacement Part. |
| PCH7970AW/C0CXB09 | | TPM SYSTEMS | 935279318005 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End of Life. Contact Marketing for Replacement Part. |
| PCH7970AW/C0CXB10 | | TPM SYSTEMS | 935279641005 | N | с | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End of Life. Contact Marketing for Replacement Part. |
| PCH7970AW/C0CXB28 | | TPM SYSTEMS | 935284053005 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End of Life. Contact Marketing for Replacement Part. |
| PCH7970EW/C0CXB14 | | ТРМ | 935283008005 | N | С | 3 | 30-Sep-11 | 31-Dec-11 | See Comments | Standard End of Life. Contact Marketing for Replacement Part. |
| PCJ7991AT/1081 | | READER CHIPS | 935261097112 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | PCJ7991AT/181/M | Standard End Of Life. Refer to PCN 201008012. |
| PCJ7991AT/1081 | PCJ7991AT/1081,118 | READER CHIPS | 935261097118 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | PCJ7991AT/181/M | Standard End Of Life. Refer to PCN 201008012. |
| PCK2001MDB | PCK2001MDB,112 | 14.318-150MHz I2C 1:10 Clock Buffer | 935262449112 | Т | М | 2 | 30-Jun-11 | 31-Dec-11 | PCK2001RDB | Limited Availability. |
| PCK2001MDB | PCK2001MDB,118 | 14.318-150MHz I2C 1:10 Clock Buffer | 935262449118 | Т | М | 2 | 30-Jun-11 | 31-Dec-11 | PCK2001RDB | Limited Availability. |
| PCK2001MDB | PCK2001MDB,512 | 14.318-150MHz I2C 1:10 Clock Buffer | 935262449512 | Т | М | 2 | 30-Jun-11 | 31-Dec-11 | PCK2001RDB | Limited Availability. |
| PCK2001MDB | PCK2001MDB,518 | 14.318-150MHz I2C 1:10 Clock Buffer | 935262449518 | Т | М | 2 | 30-Jun-11 | 31-Dec-11 | PCK2001RDB | Limited Availability. |
| PCK2023DL | PCK2023DL,512 | INTEL TITAN CLOCK | 935270212512 | Т | М | 2 | 30-Jun-11 | 31-Dec-11 | PCK2023DGG | Limited Availability. |
| PCK2023DL | PCK2023DL,518 | INTEL TITAN CLOCK | 935270212518 | Т | М | 2 | 30-Jun-11 | 31-Dec-11 | PCK2023DGG | Limited Availability. |
| PCK3807ADB | PCK3807ADB,112 | PCK3807A | 935274049112 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard End of Life. |
| PCK3807ADB | PCK3807ADB,118 | PCK3807A | 935274049118 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard End of Life. |
| PCK3807APW | PCK3807APW,112 | PCK3807A | 935274365112 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard End of Life. |
| PCK3807APW | PCK3807APW,118 | PCK3807A | 935274365118 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard End of Life. |
| PH1825AL | | 9650 <= 30V N CH TRENCHFET | 934063226115 | Т | M | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard Availability. No Replacement Part. |
| PH2030AL | | <=30V N CH TRENCHFET | 934062275115 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard Availability. No Replacement Part. |
| PH3830L | PH3830L.115 | TRENCH 3 25V | 934057827115 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | PH4030AL | Standard End of Life. |
| PH4025L | PH4025L,115 | <=30V N CH TRENCHFET | 934061156115 | Т | M | 3 | 30-Jun-11 | 31-Dec-11 | None noted | Standard End of Life. |
| PH4330L | PH4330L,115 | 9650<= 30V N CH TRENCHFET | 934061961115 | Т | M | 3 | 30-Jun-11 | 31-Dec-11 | PH4030AL | Standard End of Life. |
| PH4830L | PH4830L,115 | <=30V N CH TRENCHFET | 934061157115 | Т | M | 3 | 30-Jun-11 | 31-Dec-11 | PH5030AL | Standard End of Life. |
| PH6030L | PH6030L,115 | <=30V N CH TRENCHFET | 934061643115 | Т | M | 3 | 30-Jun-11 | 31-Dec-11 | PH6030AL | Standard End of Life. |
| PH8030L | PH8030L,115 | <=30V N CHANNEL TRENCHFET | 934058818115 | Т | M | 3 | 30-Jun-11 | 31-Dec-11 | PH6030AL | Standard End of Life. |
| PH9030L | PH9030L,115 | <=30V N CH TRENCHFET | 934061644115 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | PH9030AL | Standard End of Life. |
| 1113030L | 11130302,113 | | 334001044113 | 1 | IVI | 5 | 30-301-11 | 31-Dec-11 | THOUGHE | Standard End of Life. |
| PH9930L | PH9930L,115 | <=30V N CH TRENCHFET | 934061155115 | т | м | 3 | 30-Jun-11 | 31-Dec-11 | PH9030AL | Standard End of Life. |
| PHP36N03LT | PHP36N03LT, 127 | | 934060629127 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | PSMN022-30PL | Standard End of Life. |
| PHT11N06LT | PHT11N06LT.135 | TrenchMOS transistor | 934054590135 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | PHT8N06LT | with a higher RDSon. |
| PMEG2005EB/DG | FITTINOOET,135 | SCHOTTKY DIODE | 934061904115 | N | M | 3 | 30-Jun-11 | 31-Dec-11 | PMEG2005EB | Standard End Of Life. |
| PMEG3005AEA/DG | | Schottky diode | 934061939115 | N | M | 3 | 30-Jun-11 | 31-Dec-11 | PMEG3005AEA | Standard End Of Life. |
| PMEG3005EB/DG | | SCHOTTKY DIODE | 934061939115 | N | M | 3 | 30-Jun-11 | 31-Dec-11 | PMEG3005EB | Standard End Of Life. |
| PMEG3003EB/DG PMEG3010EJ/DG | | Schottky diode | 934061906115 | N | M | 3 | 30-Jun-11 30-Jun-11 | 31-Dec-11 31-Dec-11 | PMEG3005EB PMEG3010EJ | Standard End Of Life. |
| PMEG3020EH/DG | | SCHOTTKY DIODE | 934061825115 | N | M | 3 | 30-Jun-11 | 31-Dec-11 | PMEG3020EH | Standard End Of Life. |
| PME03020ET//DG | PMEM1505NG,115 | Schottky / Transistor module | 934058019115 | Т | M | 3 | 30-Jun-11 | 31-Dec-11 | PMEG2015EA | Standard End Of Life. |
| PMEM1505PG | PMEM1505PG,115 | · · | | I | IVI | 3 | 30-Jun-11 | 31-Dec-11 | | Standard End Of Life. |
| PMEM4010ND | | | | т. | M | 2 | 20 Jun 11 | 21 Dec 11 | DMECOOIFEA | Standard End Of Life |
| | | Schottky / Transistor module | 934058015115 | Т | M | 3 | 30-Jun-11 | 31-Dec-11 | PMEG2015EA | Standard End Of Life. |
| - | PMEM4010ND,115 | Schottky / Transistor module | 934057261115 | T | М | 3 | 30-Jun-11 | 31-Dec-11 | PMEG2015EA | Standard End Of Life. |
| PMEM4010PD | PMEM4010ND,115 PMEM4010PD,115 | Schottky / Transistor module Schottky / Transistor module | 934057261115 934057260115 | • | M M | 3 | 30-Jun-11 30-Jun-11 | 31-Dec-11 31-Dec-11 | PMEG2015EA PMEG2015EA | Standard End Of Life. Standard End Of Life. |
| PMEM4010PD PMEM4020AND | PMEM4010ND,115 PMEM4010PD,115 PMEM4020AND,115 | Schottky / Transistor module Schottky / Transistor module Schottky / Transistor module | 934057261115 934057260115 934058271115 | T T T T | M M M | 3 3 3 | 30-Jun-11 30-Jun-11 30-Jun-11 | 31-Dec-11 31-Dec-11 31-Dec-11 | PMEG2015EA PMEG2015EA PMEG4010EJ | Standard End Of Life. Standard End Of Life. Standard End Of Life. |
| PMEM4010PD PMEM4020AND PMEM4020APD | PMEM4010ND,115 PMEM4010PD,115 PMEM4020AND,115 PMEM4020APD,115 | Schottky / Transistor module Schottky / Transistor module Schottky / Transistor module Schottky / Transistor module | 934057261115 934057260115 934058271115 934058272115 | T T T T T | M M M | 3 3 3 3 | 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 | 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 | PMEG2015EA PMEG2015EA PMEG4010EJ PMEG4010EJ | Standard End Of Life. Standard End Of Life. Standard End Of Life. Standard End Of Life. |
| PMEM4010PD PMEM4020AND PMEM4020APD PMEM4020ND | PMEM4010ND,115 PMEM4010PD,115 PMEM4020AND,115 PMEM4020APD,115 PMEM4020ND,115 PMEM4020ND,115 | Schottky / Transistor module Schottky / Transistor module Schottky / Transistor module Schottky / Transistor module Schottky / Transistor module | 934057261115 934057260115 934058271115 934058272115 934057674115 | T T T T T T | M M M M | 3 3 3 3 3 3 | 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 | 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 | PMEG2015EA PMEG2015EA PMEG4010EJ PMEG4010EJ PMEG2015EA | Standard End Of Life. Standard End Of Life. Standard End Of Life. Standard End Of Life. Standard End Of Life. |
| PMEM4010PD PMEM4020AND PMEM4020APD PMEM4020ND PMEM4020PD | PMEM4010ND,115 PMEM4010PD,115 PMEM4020AND,115 PMEM4020APD,115 | Schottky / Transistor module Schottky / Transistor module | 934057261115 934057260115 934058271115 934058272115 934057674115 934057675115 | T T T T T T T | M M M M M | 3 3 3 3 3 3 3 | 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 | 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 | PMEG2015EA PMEG2015EA PMEG4010EJ PMEG4010EJ PMEG2015EA PMEG2015EA | Standard End Of Life. Standard End Of Life. |
| PMEM4010PD PMEM4020AND PMEM4020APD PMEM4020ND PMEM4020PD PMLL4148L/R | PMEM4010ND,115 PMEM4010PD,115 PMEM4020AND,115 PMEM4020APD,115 PMEM4020ND,115 PMEM4020ND,115 | Schottky / Transistor module Schottky / Transistor module SWITCHING DIODES | 934057261115 934057260115 934058271115 934058272115 934058272115 934057674115 934057675115 934062231135 | T T T T T T N | M M M M M M | 3 3 3 3 3 3 3 3 3 | 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 | 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 | PMEG2015EA PMEG2015EA PMEG4010EJ PMEG4010EJ PMEG2015EA PMEG2015EA PMEG2015EA | Standard End Of Life. Standard End Of Life. |
| PMEM4010PD PMEM4020AND PMEM4020APD PMEM4020ND PMEM4020PD PMLL4148L/R PN5320A3HN/C104 | PMEM4010ND,115 PMEM4010PD,115 PMEM4020AND,115 PMEM4020APD,115 PMEM4020ND,115 PMEM4020ND,115 | Schottky / Transistor module Schottky / Transistor module SwVITCHING DIODES NFC ICS | 934057261115 934057260115 934058271115 934058272115 934057674115 934057675115 934062231135 935282943518 | T T T T T T N N | M M M M M M M | 3 3 3 3 3 3 3 3 3 3 3 | 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 | 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 | PMEG2015EA PMEG2015EA PMEG4010EJ PMEG2015EA PMEG2015EA PMEG2015EA PMLL4148L See Comments | Standard End Of Life. Standard End Of Life. |
| PMEM4010PD PMEM4020AND PMEM4020APD PMEM4020ND PMEM4020PD PMLL4148L/R PN5320A3HN/C104 PN5320A3HN/C104 | PMEM4010ND,115 PMEM4010PD,115 PMEM4020AND,115 PMEM4020APD,115 PMEM4020ND,115 PMEM4020ND,115 | Schottky / Transistor module Schottky / Transistor module SwiTC-HING DIODES NFC ICS NFC ICS | 934057261115 934057260115 934058271115 934058272115 934057674115 934057675115 934062231135 934062231135 93408231135 | T T T T T T N N N | M M M M M M M M | 3 3 3 3 3 3 3 3 3 3 3 3 | 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 | 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 | PMEG2015EA PMEG2015EA PMEG4010EJ PMEG2015EA PMEG2015EA PMEG2015EA PMLL4148L See Comments See Comments | Standard End Of Life. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. |
| PMEM4010PD PMEM4020APD PMEM4020APD PMEM4020ND PMEM4020PD PMLL4148L/R PN5320A3HN/C104 PN5320A3HN/C104 PN5320A3HN/C104 | PMEM4010ND,115 PMEM4010PD,115 PMEM4020AND,115 PMEM4020APD,115 PMEM4020ND,115 PMEM4020ND,115 | Schottky / Transistor module Schottky / Transistor module SWITCHING DIODES NFC ICS NFC ICS NFC ICS | 934057261115 934057260115 934058271115 934058272115 9340527675115 934062231135 934062231135 935282943518 935282943551 | T T T T T N N N N | M M M M M M M M M | 3 3 3 3 3 3 3 3 3 3 3 3 3 | 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 | 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 | PMEG2015EA PMEG2015EA PMEG4010EJ PMEG4010EJ PMEG2015EA PMEG2015EA PMLL4148L See Comments See Comments See Comments | Standard End Of Life. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. |
| PMEM4010PD PMEM4020AND PMEM4020APD PMEM4020ND PMEM4020PD PMLL4148L/R PN5320A3HN/C104 PN5320A3HN/C104 PN5320A3HN/C104 PN5320A3HN/C104 | PMEM4010ND,115 PMEM4010PD,115 PMEM4020AND,115 PMEM4020APD,115 PMEM4020ND,115 PMEM4020ND,115 | Schottky / Transistor module Schottky / Transistor module SWITCHING DIODES NFC ICS NFC ICS NFC ICS NEXPERIA | 934057261115 934057260115 934058271115 934058272115 934057675115 9340657675115 934062231135 935282943518 935282943551 935282943557 935283433518 | T T T T T N N N N T | M M M M M M M M M S | 3 3 3 3 3 3 3 3 3 3 3 1 | 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 15-Dec-10 | 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 | PMEG2015EA PMEG2015EA PMEG4010EJ PMEG4010EJ PMEG2015EA PMEG2015EA PMLL4148L See Comments See Comments See Comments See Comments | Standard End Of Life. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Replacement family = CAYMAN. |
| PMEM4010PD PMEM4020AND PMEM4020APD PMEM4020ND PMEM4020PD PMLL4148L/R PN5320A3HN/C104 PN5320A3HN/C104 PN5320A3HN/C104 PN5320A3HN/C104 PNX9525E/N1 | PMEM4010ND,115 PMEM4010PD,115 PMEM4020AND,115 PMEM4020APD,115 PMEM4020ND,115 PMEM4020PD,115 PMEM4020PD,115 | Schottky / Transistor module Schottky / Transistor module SWITCHING DIODES NFC ICS NFC ICS NFC ICS NFC ICS NEXPERIA NEXPERIA | 934057261115 934057260115 934058271115 934058272115 934057674115 934057675115 934062231135 935282943551 935282943551 935282943551 935282943551 935283433518 | T T T T T N N N N N T T | M M M M M M M M M S S | 3 3 3 3 3 3 3 3 3 3 3 1 1 | 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 15-Dec-10 | 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 15-Dec-10 | PMEG2015EA PMEG2015EA PMEG4010EJ PMEG2015EA PMEG2015EA PMLL4148L See Comments See Comments See Comments None noted None noted | Standard End Of Life. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Non-Manufacturable. Replacement family = CAYMAN. Non-Manufacturable. Replacement family = CAYMAN. |
| PMEM4010PD PMEM4020AND PMEM4020APD PMEM4020ND PMLL4148L/R PN5320A3HN/C104 PN5320A3HN/C104 PN5320A3HN/C104 PN5320A3HN/C104 PN5325E/N1 PNX9525E/N1 PRLL5817 | PMEM4010ND,115 PMEM4010PD,115 PMEM4020AND,115 PMEM4020APD,115 PMEM4020ND,115 PMEM4020PD,115 PMEM4020PD,115 PMEM4020PD,115 | Schottky / Transistor module Schottky / Transistor module SWITCHING DIODES NFC ICS NFC ICS NFC ICS NEXPERIA NEXPERIA Schottky diode | 934057261115 934057260115 934058271115 934058272115 934057674115 934057675115 934062231135 935282943551 935282943551 935282943557 935283433518 93528343357 933968000115 | T T T T T N N N N N T T T | M M M M M M M M S S S M | 3 3 3 3 3 3 3 3 3 3 3 3 1 1 1 3 | 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 15-Dec-10 15-Dec-10 30-Jun-11 | 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 15-Dec-10 15-Dec-10 31-Dec-11 | PMEG2015EA PMEG2015EA PMEG4010EJ PMEG2015EA PMEG2015EA PMLL4148L See Comments See Comments See Comments None noted None noted PMEG4030ER | Standard End Of Life. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Non-Manufacturable. Replacement family = CAYMAN. Non-Manufacturable. Replacement family = CAYMAN. Standard End Of Life. |
| PMEM4010PD PMEM4020AND PMEM4020APD PMEM4020ND PMLL4148L/R PN5320A3HN/C104 PN5320A3HN/C104 PN5320A3HN/C104 PN5325E/N1 PNX9525E/N1 PRLL5817 PRLL5817 | PMEM4010ND,115 PMEM4010PD,115 PMEM4020AND,115 PMEM4020APD,115 PMEM4020ND,115 PMEM4020PD,115 PMEM4020PD,115 PMEM4020PD,115 PMEM4020PD,115 PMEM4020PD,115 | Schottky / Transistor module Schottky / Transistor module SwITCHING DIODES NFC ICS NFC ICS NFC ICS NFC ICS NEXPERIA NEXPERIA Schottky diode | 934057261115 934057260115 934058271115 934058272115 934057674115 934057675115 934057675115 934062231135 935282943551 935282943551 935283433518 935283433557 933968000115 933968000135 | T T T T T N N N N N T T | M M M M M M M M M S S S S M M | 3 3 3 3 3 3 3 3 3 3 3 3 1 1 1 3 3 3 | 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 15-Dec-10 30-Jun-11 30-Jun-11 | 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-10 31-Dec-10 31-Dec-11 | PMEG2015EA PMEG2015EA PMEG4010EJ PMEG2015EA PMEG2015EA PMLL4148L See Comments See Comments None noted PMEG4030ER PMEG4030ER | Standard End Of Life. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Non-Manufacturable. Replacement family = CAYMAN. Non-Manufacturable. Replacement family = CAYMAN. Standard End Of Life. |
| PMEM4010PD PMEM4020APD PMEM4020APD PMEM4020PD PML4148L/R PN5320A3HN/C104 PN5320A3HN/C104 PN5320A3HN/C104 PN5320A3HN/C104 PNX9525E/N1 PNX9525E/N1 PNL15817 PRLL5817 PRLL5818 | PMEM4010ND,115 PMEM4010PD,115 PMEM4020AND,115 PMEM4020APD,115 PMEM4020ND,115 PMEM4020PD,1 | Schottky / Transistor module Schottky / Transistor module SWITC-HING DIODES NFC ICS NFC ICS NFC ICS NFC ICS NFC ICS NFC ICS NEXPERIA NEXPERIA Schottky diode Schottky diode | 934057261115 934057260115 934058271115 934058272115 934057674115 934057675115 934057675115 934062231135 934062231135 935282943551 935282943557 935283433518 935283433557 933968000115 933968000115 | T T T T T T N N N N N N T T T T T | M M M M M M M M M S S S S M M M | 3 3 3 3 3 3 3 3 3 3 1 1 1 3 3 3 3 3 3 | 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 15-Dec-10 15-Dec-10 30-Jun-11 30-Jun-11 30-Jun-11 | 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-10 15-Dec-10 31-Dec-11 31-Dec-11 | PMEG2015EA PMEG2015EA PMEG4010EJ PMEG2015EA PMEG2015EA PME2015EA PMLL4148L See Comments See Comments See Comments None noted None noted PMEG4030ER PMEG4030ER PMEG4030ER | Standard End Of Life. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Non-Manufacturable. Replacement family = CAYMAN. Non-Manufacturable. Replacement family = CAYMAN. Standard End Of Life. Standard End Of Life. |
| PMEM4010PD PMEM4020APD PMEM4020APD PMEM4020ND PMEM4020PD PMLL4148L/R PN5320A3HN/C104 PN5320A3HN/C104 PN5320A3HN/C104 PN5320A3HN/C104 PN5325E/N1 PNX9525E/N1 PRLL5817 PRLL5817 PRLL5818 PRLL5819 | PMEM4010ND,115 PMEM4010PD,115 PMEM4020AND,115 PMEM4020APD,115 PMEM4020ND,115 PMEM4020PD,1 | Schottky / Transistor module Schottky / Transistor module SwiTC-HING DIODES NFC ICS NFC ICS NFC ICS NFC ICS NFC ICS NFC ICS NFC ICS NFC ICS Schottky diode Schottky diode Schottky diode | 934057261115 934057260115 934058271115 934058272115 934057674115 934057675115 934062231135 934062231135 934062231135 935282943551 935282943557 935283433518 935283433557 933968000135 933968000135 933968010115 933968002115 | T T T T T N N N N N T T T | M M M M M M M M M S S S S M M M M | 3 3 3 3 3 3 3 3 3 3 1 1 1 3 3 3 3 3 3 3 | 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 15-Dec-10 15-Dec-10 15-Dec-10 30-Jun-11 30-Jun-11 30-Jun-11 | 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-10 31-Dec-10 31-Dec-11 | PMEG2015EA PMEG2015EA PMEG4010EJ PMEG4010EJ PMEG2015EA PMEG2015EA PMLL4148L See Comments See Comments See Comments None noted PMEG4030ER PMEG4030ER PMEG4030ER PMEG4030ER | Standard End Of Life. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Non-Manufacturable. Replacement family = CAYMAN. Non-Manufacturable. Replacement family = CAYMAN. Standard End Of Life. Standard End Of Life. Standard End Of Life. |
| PMEM4010PD PMEM4020APD PMEM4020APD PMEM4020PD PML4148L/R PN5320A3HN/C104 PN5320A3HN/C104 PN5320A3HN/C104 PN5320A3HN/C104 PNX9525E/N1 PNX9525E/N1 PNL15817 PRLL5817 PRLL5818 | PMEM4010ND,115 PMEM4010PD,115 PMEM4020AND,115 PMEM4020APD,115 PMEM4020ND,115 PMEM4020PD,1 | Schottky / Transistor module Schottky / Transistor module SWITC-HING DIODES NFC ICS NFC ICS NFC ICS NFC ICS NFC ICS NFC ICS NEXPERIA NEXPERIA Schottky diode Schottky diode | 934057261115 934057260115 934058271115 934058272115 934057674115 934057675115 934057675115 934062231135 934062231135 935282943551 935282943557 935283433518 935283433557 933968000115 933968000115 | T T T T T T N N N N N N T T T T T | M M M M M M M M M S S S S M M M | 3 3 3 3 3 3 3 3 3 3 1 1 1 3 3 3 3 3 3 | 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 30-Jun-11 15-Dec-10 15-Dec-10 30-Jun-11 30-Jun-11 30-Jun-11 | 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-11 31-Dec-10 15-Dec-10 31-Dec-11 31-Dec-11 | PMEG2015EA PMEG2015EA PMEG4010EJ PMEG2015EA PMEG2015EA PME2015EA PMLL4148L See Comments See Comments See Comments None noted None noted PMEG4030ER PMEG4030ER PMEG4030ER | Standard End Of Life. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Standard End Of Life. Contact your local NXP sales office. Non-Manufacturable. Replacement family = CAYMAN. Non-Manufacturable. Replacement family = CAYMAN. Standard End Of Life. Standard End Of Life. |

| SAA7709H/N104 | SAA7709H/N104,557 | DIRAC-2 | 935269694557 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
|------------------|-----------------------|---------------------------------|--------------|---|----------|------------|------------------------|-----------|------------------|--|
| SC18IS601IBS | SC18IS601IBS,128 | SPI-I2C MASTER BRIDGE,4M /GPIO | 935286979128 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None | Standard End of Life. |
| SC18IS601IBS | SC18IS601IBS,151 | SPI-I2C MASTER BRIDGE,4M /GPIO | 935286979151 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None | Standard End of Life. |
| SC18IS601IBS | SC18IS601IBS,157 | SPI-I2C MASTER BRIDGE,4M /GPIO | 935286979157 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None | Standard End of Life. |
| SC18IS601IPW | SC18IS601IPW,112 | SC18IS601I | 935280628112 | т | S | 3 | 30-Sep-11 | 31-Dec-11 | None | Standard End of Life. |
| SC18IS601IPW | SC18IS601IPW,128 | SC18IS601I | 935280628128 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None | Standard End of Life. |
| SC68C2550BIB48 | SC68C2550BIB48,128 | 2.5/3.3/5V DUAL ART W/64 B FIFO | 935278765128 | т | М | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard End of Life. |
| SC68C2550BIB48 | SC68C2550BIB48,151 | 2.5/3.3/5V DUAL ART W/64 B FIFO | 935278765151 | т | М | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard End of Life. |
| SC68C2550BIB48 | SC68C2550BIB48,157 | 2.5/3.3/5V DUAL ART W/64 B FIFO | 935278765157 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard End of Life. |
| SE97TP | SE97TP,147 | SE97 | 935286725147 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | SE97BTP | Standard End of Life. |
| SE97TP/S900 | | SE97 | 935290545547 | Т | M | 3 | 30-Jun-11 | 31-Dec-11 | SE97BTP | Standard End of Life. |
| SE97TP/S901 | | SE97 | 935290546547 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | SE97BTP | Standard End of Life. |
| SLEV400/HAB | SLEV400/HAB,122 | CL READER SYSTEMS | 935270411122 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | See Comments | Standard End of Life. Contact your local NXP sales office. |
| SSTVF16859BS | SSTVF16859BS,118 | SSTVF16859BS | 935276956118 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard End of Life. |
| SSTVF16859BS | SSTVF16859BS,151 | SSTVF16859BS | 935276956151 | T | M | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard End of Life. |
| SSTVF16859BS | SSTVF16859BS,157 | SSTVF16859BS | 935276956157 | т | M | 3 | 30-Jun-11 | 31-Dec-11 | None | Standard End of Life. |
| TDA1308AUK | TDA1308AUK,027 | TDA1308A | 935280856027 | T | M | 1 | 15-Dec-10 | 15-Dec-10 | None noted | Non-Manufacturable. |
| TDA18254HN/C1 | TDA18254HN/C1,518 | SiTuner for Hybrid Cable | 935289589518 | T | S | 3 | 30-Sep-11 | 31-Dec-11 | TDA18254AHN/C1 | Standard End of Life. |
| TDA18254HN/C1 | TDA18254HN/C1,551 | SiTuner for Hybrid Cable | 935289589551 | Т | s | 3 | 30-Sep-11 30-Sep-11 | 31-Dec-11 | TDA18254AHN/C1 | Standard End of Life. |
| TDA18254HN/C1 | TDA18254HN/C1,557 | SiTuner for Hybrid Cable | 935289589557 | T | s | 3 | 30-Sep-11 | 31-Dec-11 | TDA18254AHN/C1 | Standard End of Life. |
| TDA16234HIN/C1 | TDA 182341 IN/C 1,337 | | 933209309337 | 1 | 3 | 5 | 30-3ep-11 | 31-Dec-11 | TDA 10234ALIN/CT | Standard End of Life. |
| TDA6650ATT/C3 | | DIG TERRESTRIAL MOPLL FOR ISDBT | 935277152118 | т | S | 3 | 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
| TD 100501 TT (00 | | | 005077450540 | Ŧ | <u> </u> | 2 | 20.0 44 | 04 Dec 44 | Name and a | Oten dead End of Life |
| TDA6650ATT/C3 | | DIG TERRESTRIAL MOPLL FOR ISDBT | 935277152518 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
| | | | | - | | | | | | |
| TDA6650TT/C3 | | MOPLL DIGITAL STANDARD | 935277146118 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
| | | | | - | | | | | | |
| TDA6650TT/C3 | | MOPLL DIGITAL STANDARD | 935277146518 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
| | | | | _ | _ | _ | | | | |
| TDA6651ATT/C3 | | DIG TERRESTRIAL MOPLL FOR ISDBT | 935277148118 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
| | | | | | | | | | | |
| TDA6651ATT/C3 | | DIG TERRESTRIAL MOPLL FOR ISDBT | 935277148518 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
| | | | | | | | | | | |
| TDA6651ATT/C3/S2 | | DIG TERRESTRIAL MOPLL FOR ISDBT | | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
| TDA6651ATT/C3/S2 | | DIG TERRESTRIAL MOPLL FOR ISDBT | | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
| TDA6651ATT/C3/S3 | | DIG TERRESTRIAL MOPLL FOR ISDBT | 935282393118 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
| TDA6651TT/C3 | | MOPLL FOR DIGITAL TERRESTRIAL | 935277153118 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
| TDA6651TT/C3 | | MOPLL FOR DIGITAL TERRESTRIAL | 935277153518 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
| TDA6651TT/C3/S2 | | MOPLL FOR DIGITAL TERRESTRIAL | 935277147118 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
| TDA6651TT/C3/S2 | | MOPLL FOR DIGITAL TERRESTRIAL | 935277147518 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
| TDA6651TT/C3/S3 | | MOPLL FOR DIGITAL TERRESTRIAL | 935281471118 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
| | | | | | | | | | | |
| TDA6651TT/C3/S3 | | MOPLL FOR DIGITAL TERRESTRIAL | 935281471518 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None noted | Standard End of Life. |
| TDA8024T/C1/S1 | | CT READER IC'S ANALOG | 935293005118 | N | S | 1 | 15-Dec-10 | 15-Dec-10 | TDA8024T/C1 | Non-Manufacturable. Contact your local NXP sales office |
| TDA8541T/N1/02 | | MULTI MEDIA POWER AMPLIFIERS | 935291389118 | N | С | 1 | 15-Dec-10 | 15-Dec-10 | TDA8541T/N1 | Non-Manufacturable. |
| | | DEMODUL NEGATIVE MODULATION | | | | | | | | |
| TDA9885HN/V3 | TDA9885HN/V3,118 | VIF&SIF | 935270556118 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | TDA9885NH/V5 | Standard End of Life. |
| TDA9885HN/V3 | | VIF&SIF | 935270556151 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | TDA9885HN/V5 | Standard End of Life. |
| TDA9885HN/V3 | | VIF&SIF | 935270556157 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | TDA9885HN/V5 | Standard End of Life. |
| TDA9885HN/V3 | TDA9885HN/V3,518 | VIF&SIF | 935270556518 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | TDA9885HN/V5 | Standard End of Life. |
| TDA9885T/V3 | TDA9885T/V3,118 | MOD | 935270550118 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | TDA9885T/V5 | Standard End of Life. |
| TDA9885TS/V3 | TDA9885TS/V3,118 | MOD | 935270551118 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | TDA9885TS/V5 | Standard End of Life. |
| TDA9885TS/V3 | TDA9885TS/V3,518 | MOD | 935270551518 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | TDA9885TS/V5 | Standard End of Life. |
| TDA9886HN/V4 | TDA9886HN/V4,118 | DEMODULATOR VIF AND SIF | 935272382118 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | TDA9886HN/V5 | Standard End of Life. |
| TDA9886HN/V4 | TDA9886HN/V4,518 | DEMODULATOR VIF AND SIF | 935272382518 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | TDA9886HN/V5 | Standard End of Life. |
| TDA9886T/V4 | TDA9886T/V4,112 | MULTISTANDARD AFRIC VISION IF | 935272371112 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | TDA9886T/V5 | Standard End of Life. |
| TDA9886T/V4 | TDA9886T/V4,118 | MULTISTANDARD AFRIC VISION IF | 935272371118 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | TDA9886T/V5 | Standard End of Life. |
| TDA9886TS/V4 | TDA9886TS/V4,112 | MULTISTANDARD AFRIC VISION IF | 935272372112 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | TDA9886TS/V5 | Standard End of Life. |
| | 1 | | | | | . <u> </u> | | | | |

| TDA9886TS/V4 | TDA9886TS/V4,118 | MULTISTANDARD AFRIC VISION IF | 935272372118 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | TDA9886TS/V5 | Standard End of Life. |
|--------------------|----------------------|-------------------------------|--------------|---|---|---|-----------|-----------|--------------------|--|
| TDA9886TS/V4 | TDA9886TS/V4,518 | MULTISTANDARD AFRIC VISION IF | 935272372518 | N | S | 3 | 30-Sep-11 | 31-Dec-11 | TDA9886TS/V5 | Standard End of Life. |
| TEF6860HL/V2S/S1 | | TUNER IC | 935290674518 | Т | С | 2 | 30-Sep-11 | 31-Dec-11 | TEF6862HL/V1S | available stock. |
| TEF7000HN/V2T | | LEAF DICE | 935290686518 | N | S | 1 | 15-Dec-10 | 15-Dec-10 | TEF7000HN/V3 | Non-Manufacturable. |
| TEF7000HN/V2T | | LEAF DICE | 935290686557 | N | S | 1 | 15-Dec-10 | 15-Dec-10 | TEF7000HN/V3 | Non-Manufacturable. |
| TEF7000HN/V2T/S422 | | LEAF DICE | 935290687518 | Ν | с | 1 | 15-Dec-10 | 15-Dec-10 | TEF7000HN/V2S/S422 | Non-Manufacturable. Discontinuation of one version only, product family still in continuous production. |
| UBA2072T/N1 | UBA2072T/N1,518 | CCFL DRIVER | 935280565518 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None | Standard End of Life. |
| UBA2074AT/N1 | UBA2074AT/N1,518 | HV CCFL DRIVER | 935284182518 | Т | S | 3 | 30-Sep-11 | 31-Dec-11 | None | Standard End of Life. |
| UDA1334U/N2 | | UDA1334U | 935286977025 | Т | М | 3 | 30-Jun-11 | 31-Dec-11 | None noted | Standard End of Life. |
| UJA1075TW/3V3 | UJA1075TW/3V3,112 | HS-CAN SBCS | 935286524112 | Т | S | 1 | 15-Dec-10 | 15-Dec-10 | UJA1075ATW/3V3 | Non-Manufacturable. Family changed from 1075 to 1075A. |
| UJA1075TW/3V3 | UJA1075TW/3V3,118 | HS-CAN SBCS | 935286524118 | Т | S | 1 | 15-Dec-10 | 15-Dec-10 | UJA1075ATW/3V3 | Non-Manufacturable. Family changed from 1075 to 1075A. |
| UJA1075TW/3V3/WD | UJA1075TW/3V3/WD,112 | HS-CAN SBCS | 935286525112 | Т | S | 1 | 15-Dec-10 | 15-Dec-10 | UJA1075ATW/3V3/WD | Non-Manufacturable. Family changed from 1075 to 1075A. |
| UJA1075TW/3V3/WD | UJA1075TW/3V3/WD:118 | HS-CAN SBCS | 935286525118 | Т | S | 1 | 15-Dec-10 | 15-Dec-10 | UJA1075ATW/3V3/WD | Non-Manufacturable. Family changed from 1075 to 1075A. |
| UJA1075TW/5V0 | UJA1075TW/5V0,112 | HS-CAN SBCS | 935286522112 | Т | S | 1 | 15-Dec-10 | 15-Dec-10 | UJA1075ATW/5V0 | Non-Manufacturable. Family changed from 1075 to 1075A. |
| UJA1075TW/5V0 | UJA1075TW/5V0,118 | HS-CAN SBCS | 935286522118 | Т | S | 1 | 15-Dec-10 | 15-Dec-10 | UJA1075ATW/5V0 | Non-Manufacturable. Family changed from 1075 to 1075A. |
| UJA1075TW/5V0/WD | UJA1075TW/5V0/WD:112 | HS-CAN SBCS | 935286523112 | Т | S | 1 | 15-Dec-10 | 15-Dec-10 | UJA1075ATW/5V0 | Non-Manufacturable. Family changed from 1075 to 1075A. |
| UJA1075TW/5V0/WD | UJA1075TW/5V0/WD,118 | HS-CAN SBCS | 935286523118 | Т | S | 1 | 15-Dec-10 | 15-Dec-10 | UJA1075ATW/5V0/WD | Non-Manufacturable. Family changed from 1075 to 1075A. |
| UJA1076TW/3V3 | UJA1076TW/3V3,112 | HS-CAN SBCS | 935287874112 | Т | S | 1 | 15-Dec-10 | 15-Dec-10 | UJA1076ATW/3V3 | Non-Manufacturable. Family changed from 1076 to 1076A. |
| UJA1076TW/3V3 | UJA1076TW/3V3,118 | HS-CAN SBCS | 935287874118 | Т | S | 1 | 15-Dec-10 | 15-Dec-10 | UJA1076ATW/3V3 | Non-Manufacturable. Family changed from 1076 to 1076A. |
| UJA1076TW/3V3/WD | UJA1076TW/3V3/WD,112 | HS-CAN SBCS | 935287875112 | Т | S | 1 | 15-Dec-10 | 15-Dec-10 | UJA1076ATW/3V3/WD | Non-Manufacturable. Family changed from 1076 to 1076A. |
| UJA1076TW/3V3/WD | UJA1076TW/3V3/WD:118 | HS-CAN SBCS | 935287875118 | Т | S | 1 | 15-Dec-10 | 15-Dec-10 | UJA1076ATW/3V3/WD | Non-Manufacturable. Family changed from 1076 to 1076A. |
| UJA1076TW/5V0 | UJA1076TW/5V0,112 | HS-CAN SBCS | 935287872112 | Т | S | 1 | 15-Dec-10 | 15-Dec-10 | UJA1076ATW/5V0 | Non-Manufacturable. Family changed from 1076 to 1076A. |
| UJA1076TW/5V0 | UJA1076TW/5V0,118 | HS-CAN SBCS | 935287872118 | Т | S | 1 | 15-Dec-10 | 15-Dec-10 | UJA1076ATW/5V0 | Non-Manufacturable. Family changed from 1076 to 1076A. |
| UJA1076TW/5V0/WD | UJA1076TW/5V0/WD:112 | HS-CAN SBCS | 935287873112 | Т | S | 1 | 15-Dec-10 | 15-Dec-10 | UJA1076ATW/5V0/WD | Non-Manufacturable. Family changed from 1076 to 1076A. |
| UJA1076TW/5V0/WD | UJA1076TW/5V0/WD,118 | HS-CAN SBCS | 935287873118 | Т | S | 1 | 15-Dec-10 | 15-Dec-10 | UJA1076ATW/5V0/WD | Non-Manufacturable. Family changed from 1076 to 1076A. |
| UJA1078TW/3V3 | UJA1078TW/3V3,112 | HS-CAN SBCS | 935287771112 | Т | S | 1 | 15-Dec-10 | 15-Dec-10 | UJA1078ATW/3V3 | Non-Manufacturable. Family changed from 1078 to 1078A. |
| UJA1078TW/3V3 | UJA1078TW/3V3,118 | HS-CAN SBCS | 935287771118 | Т | S | 1 | 15-Dec-10 | 15-Dec-10 | UJA1078ATW/3V3 | Non-Manufacturable. Family changed from 1078 to 1078A. |
| UJA1078TW/3V3/WD | UJA1078TW/3V3/WD,112 | HS-CAN SBCS | 935287772112 | Т | S | 1 | 15-Dec-10 | 15-Dec-10 | UJA1078ATW/3V3/WD | Non-Manufacturable. Family changed from 1078 to 1078A. |
| UJA1078TW/3V3/WD | UJA1078TW/3V3/WD:118 | HS-CAN SBCS | 935287772118 | Т | S | 1 | 15-Dec-10 | 15-Dec-10 | UJA1078ATW/3V3/WD | Non-Manufacturable. Family changed from 1078 to 1078A. |
| UJA1078TW/5V0 | UJA1078TW/5V0,112 | HS-CAN SBCS | 935287768112 | Т | S | 1 | 15-Dec-10 | 15-Dec-10 | UJA1078ATW/5V0 | Non-Manufacturable. Family changed from 1078 to 1078A. |
| UJA1078TW/5V0 | UJA1078TW/5V0,118 | HS-CAN SBCS | 935287768118 | Т | S | 1 | 15-Dec-10 | 15-Dec-10 | UJA1078ATW/5V0 | Non-Manufacturable. Family changed from 1078 to 1078A. |
| UJA1078TW/5V0/WD | UJA1078TW/5V0/WD,112 | HS-CAN SBCS | 935287769112 | Т | С | 2 | 30-Sep-11 | 31-Dec-11 | UJA1078ATW/5V0/WD | Limited Availability. Family changed from 1078 to 1078A. |
| UJA1078TW/5V0/WD | UJA1078TW/5V0/WD:118 | HS-CAN SBCS | 935287769118 | Т | С | 2 | 30-Sep-11 | 31-Dec-11 | UJA1078ATW/5V0/WD | Limited Availability. Family changed from 1078 to 1078A. |